



## Certificate of Compliance


Certificate Number: 0174-02-19-ATP-MK

**Type of Certification:** Full Certificate - Initial certification audit

For the recycling plant:

**Fast-Fol Gadomscy Sp. J.**  
Ul. Graniczna 1 D  
PL 06-500 Mława POLAND

Process	Input material	Presentation	Nominal capacity (t/a)	Post-consumer material accepted for recycling in previous 12 months (t)	Output of recycling process	Post-consumer recycled output (t)	Pre and post-consumer recycled output (t)	Level of traceability (1 to 2)	Washed material
Recycling and extrusion of PE waste plastic	Post consumer LDPE	Ballots	7 416	7 076,180	REGRANULAT LDPE	3 429,176	3 429,176	1	washed

Audited by: Marcin Konopczyński	Auditor's logo: 
Date of audit: [06/02/2018]	
Period of evaluation: [01/01/2017]to 31/12/2017]	
Period of validity: [06/02/2018] to [06/02/2019]	

The recycling process and associated management systems of the aforementioned company for the waste plastic and site shown has been audited and have met the required standards for certification under the EuCertPlast Scheme for European Plastic Recyclers.

This plant is the last recipient of plastics waste and produces products.

[Address and contact details for Auditor]    [Address and contact details for EuCertPlast]

**Marcin Konopczyński**  
Almaland sp. z o.o.  
Złotniki, ul. Kochanowskiego 5,  
62-002 Suchy Las - Poland  
Tel.: +48 61 656 95 40  
Fax: +48 61 656 95 50  
E-mail: [biuro@almaland.pl](mailto:biuro@almaland.pl)  
Website: [www.almaland.pl](http://www.almaland.pl)

**EuCertPlast**  
Avenue de Cortenberg, 71  
1000 Brussel – Belgium  
Tel.: +32 2 732 41 24  
Fax: +32 2 732 42 18  
E-mail: [info@plasticsrecyclers.be](mailto:info@plasticsrecyclers.be)  
Website: [www.eucertplast.eu](http://www.eucertplast.eu)